

•3. Existing road surface with minor rutting. Ch 70



·4. Paved ditch in good condition. Ch. 90



 Looking downhill to public road. Showing road surface washed away and start of deep ruts.



2. Deep ruts at Ch. 50

Ref: 237/KGC

Military Road at Culachy, Fort Augustus.